

DMMS IEC 60811-504:2012

Electric and optical fibre cables - Test methods for non-metallic materials - Part 504:  
Mechanical tests - Bending tests at low temperature for insulation and sheaths

### **Scope**

This Part 504 of IEC 60811 gives the procedure for performing bending tests at low temperature on extruded insulations and sheaths.