

DMMS IEC 60811-508:2012+AMD1:2017 CSV Consolidated version

Electric and optical fibre cables - Test methods for non-metallic materials - Part 508:  
Mechanical tests - Pressure test at high temperature for insulation and sheaths

### **Scope**

This Part 508 of IEC 60811 gives the procedure for a pressure test at high temperature, which typically applies to thermoplastic compounds used for insulating and sheathing materials

Public Comment Use Only